

▲ Replaceable Soldering Tips for QUICK TS2400

Q型
(马蹄型)



504-6C		504-8C		504-10C	

I型
(批针型)



504-6D		504-8D		504-10D		504-12D	
504-6DU		504-10DU					

K型
(刀型)



504-K	